


# The existing park



- |                                      |                         |
|--------------------------------------|-------------------------|
| <b>1</b> Sunken Sports Court         | <b>6</b> Entrance gates |
| <b>2</b> Steep Ramp (not accessible) | <b>7</b> Footpath       |
| <b>3</b> Steps                       | <b>8</b> Lawn           |
| <b>4</b> Play area                   | <b>9</b> Planting       |
| <b>5</b> Seating                     |                         |

## Key facts

- Sports court 1.5 metres below park level, limiting views across the park.
- Brick wall to playground restricts views into the sports court.
- Steep ramp access makes it difficult for many people to get into the sports court.
- The planting makes it difficult to see across the park.
- Play equipment.
- Footpaths lead to dead-ends.

**View A:** The location of the planting prevents clear views across the park.



**View B:** Ballcourt level and location of brick walls prevent views across the park.

